

Manhole Inspection Summary

Manhole # S17M__029MH

Printed On: 2/12/2009

Page 1 of 3

Inspection Is Incomplete Rating: **2) Good**

Record Plat: **17M** Node: **029** Status: **Found**

Insp Date: **4/11/08 2:20 PM**

Incomplete Comments

Crew: **REI**
Inspector: **paulfry**
Firm: **REI**

Location Address: **2624 lehman st**

Cross Street: **millington**

Manhole Type: **Terminal** Location: **Sidewalk**

Ground Conditions: **Dry**

Prev. Rehab Weather: **Dry**

Subject To Ponding: **None**

Comments

Cover Shape: **Circular** Diameter: **24** (in.) Length: **0** (in.) Dist A/B Grade: **0** (in.)

Type: **Sanitary** Condition: **Sound** Cover Material: **Cast Iron**

Properties: Bolted Vented Water Tight Water Tight Insert

Frame Offset: **0** (in.) Condition: Sound Cracked Leaks

Chimney / Frame Adjustment Exists Material: Parged Height: **0** (in.)

Condition: Sound Cracked Root Intrusion Loose Brick Deteriorated

Infiltration: None Joint Cracks Mortar Roots Wall

Corbel Material: **Brick** Parged Type: **Concentric/Eccentric**

Condition: Sound Cracked Root Intrusion Loose Brick Deteriorated

Infiltration: None Joint Cracks Mortar Roots Wall

Barrel Material: **Brick** Parged

Shape: **Circular** Diameter: **48** (in.) Length: **0** (in.)

Condition: Sound Cracked Root Intrusion Loose Brick Deteriorated

Infiltration: None Joint Cracks Mortar Roots Wall

Bench Exists Material: Parged

Condition: Sound Cracked Root Intrusion Deteriorated Leaks Debris

Channel Material: **Brick** Parged

Channel Exposure: **Fully Open** Junc Dist: **0** nearest .5 ft. Azimuth: **0**

Condition: Sound Cracked Root Intrusion Deteriorated Leaks Debris

Steps Count: **2** Missing: **0** Corroded

Surcharge Evidence Of Surcharge Depth: **0** (ft.) Active Surcharge Present

Location View



Top View



Manhole Inspection Summary

Manhole # S17M__029MH

Printed On: 2/12/2009

Page 3 of 3

8 in. Circular Gravity Sewer
Pipe Out @ 12 O'Clock

12 O'Clock Outflow



Pipe Height: **8.4** (in.) Rod and Bar (Angled)
Pipe Material: **Clay** Pipe Lined
Invert Depth: **5.62** (ft.) Flow Characteristics:
Deposits: None Mud Sludge Debris Grease
Silt Depth: **0** (in.) Deposits Extent:
Infiltration: Pipe Seal Cond:

Drop: **None**

Connects To: **Manhole**
 Possible Illicit Connection
